

Agfa Corporation
200 Ballardvale Street
Wilmington, Ma 01887
Dkt#: XP-1108 Filed: June 27, 2003
Titled: System and Method For Determining The Operational
Status Of An Imaging System Including an Illumination Modulator




FIG. 1

Agfa Corporation
200 Ballardvale Street
Wilmington, Ma 01887
Dkt#: XP-1108 Filed: June 27, 2003
Titled: System and Method For Determining The Operational
Status Of An Imaging System Including an Illumination Modulator





FIG. 2

Agfa Corporation
200 Ballardvale Street
Wilmington, Ma 01887
Dkt#: XP-1108 Filed: June 27, 2003
Titled: System and Method For Determining The Operational
Status Of An Imaging System Including an Illumination Modulator



Dkt#: XP-1108 Filed: June 27, 2003
Titled: System and Method For Determining The Operational
Status Of An Imaging System Including an Illumination Modulator




FIG. 5A

Wilmington, Ma 01887

Dkt#: XP-1108 Filed: June 27, 2003

Titled: System and Method For Determining The Operational Status Of An Imaging System Including an Illumination Modulator




FIG. 5B

200 Ballardvale Street
Wilmington, Ma 01887
Dkt#: XP-1108 Filed: June 27, 2003
Titled: System and Method For Determining The Operational Status Of An Imaging System Including an Illumination Modulator




FIG. 5C